


NOTE:
DUE TO CROSS SPAR IN FRAME UNDER PLATE
I HAD TO SHORTEN (CUT OFF) THESE BOLTS!



NOTE:
I BOUGHT A LONGER BOLT HERE